

SPA/WALL PROJECT

- 1. HISTORY: The spa/wall project was delayed due to the budget challenge precipitated from an insurance crisis in 2023. This insurance dilemma has been resolved for the current term and the coming year will be dealt with in the 2024 budget. The goal is to reengage the spa/wall reconstruction in 2024 to get back on track and save costs for the future. To that end, the WP Board authorized a spa committee to be organized and tasked with formulating a plan of action. The committee outlined an approach to reflect current conditions, needs, and membership input. The first step involved a spa survey to the membership which was accomplished this spring. The committee then summarized the results of the survey in order to facilitate a plan reflecting owner feedback. The next effort entailed a meeting with our selected design build contractor, Lydig Construction, and the architect to discuss survey results and get their professional opinion The meeting was helpful in discussing changes to the original plan and incorporating member input into a final design for presentation to the White Pine and 5 Needles owners. Our professional advisors were very receptive to our concepts and guided us through the evaluation. Through this process a new design was submitted to the board last fall. The Board really liked this design and provisionally approved pending the pricing. The costs for the plan came in late December for review and potential planning for a special meeting. The plan costs were viable, nevertheless, the Board felt another plan and pricing would provide another workable alternative for the membership as well as being in line with the original projection from a couple of years ago. Additionally, the two plan options given the Board were very workable and both would solve our pending and future challenges. The quote for the second option came in late February here the need to get the special Spa meeting scheduled in April.
- 2. THE TEAM: Through the years, there was a collaborative effort of several individuals, groups, and professional advisors to monitor and develop a plan for the ultimate need to replace and remodel the spa area. Please review the following contributors:
 - MEMBERSHIP: The White Pine owners have, for years, provided input and ideas for the spa.
 The recent membership survey assisted in developing a final design that mirrored the responses.
 - 2) SPA COMMITTEE: Formed in March of 2023, the Committee conducted a membership survey for the spa area. This effort resulted in the summarized results. (see attachments) During the Summer and early Fall, several meetings were held with Lydig and the architect to review changes and finalize the proposed design. The final design incorporated the membership survey with input from our professional advisors. The Spa Committee consisted of Board members and owners as follows:

Kris Pereira Randy Haddock Mike Thayer Tom Tierney Rob Sorensen

3) BOARD OF DIRECTORS: In addition to the work described in the History section, the Board conducted a diligent research and bidding process. Initially, four large and reputable commercial contractors were asked to propose a design build proposal for the spa/wall replacement. Ginno, Walker, Jackson, and Lydig Construction Companies were approached for the project. With the original and subsequent design build bid, Lydig Construction was awarded the work. Lydig brought in Bernard Wills as the architects. When developing the Needles, SMR brought in GeoEngineering to provide a geotechnical report on the retaining wall condition. Previously, AllWest monitored and reported the potential movement with the White Pine foundation.

The bottom line is that White Pine has worked with an A-team of construction professionals developing a workable plan for the spa/wall project. Please utilize the websites below for your own evaluation of the White Pine advisors.

LYDIG CONSTRUCTION (www.lydig.com)
BERNARDO WILLS ARCHITECTS (www.bernardowills.com)

- ATTACHMENTS:
 - 1. SURVEY RESULTS
 - 2. OPTION 1
 - 3. OPTION 2
 - 4. SPA/WALL CONDITION
 - 5. OPTION 1 ASSESSMENT SPREADSHEET
 - 6. OPTION 2 ASSESSMENT SPREADSHEET
- 4. DESIGN CHANGES: The spa committee and Lydig Construction's team have come up with two options for the replacement of the existing spas, maintaining the existing spas and wall is not seen as a viable option. These options have taken into account the feedback from the owner's survey and have implemented several changes that streamlined the design from the original concept to help reduce overall cost. Please note that we have included a contingency amount in each option to offset any unknowns as well as minimize cost increases that may arise prior to construction.

 The primary difference between Option 1 and Option 2 is the number of tubs and the amount of surface area provided by each. the owner's patio area remains the same for each Option. Option 2 does not allow for future expansion and does not increase the user capacity.

The following are changes to the original design and clarifications for these options:

- 1) Eliminate all fire pits with the exception of providing gas piping and electrical for a potential owner's fire pit on the owner's patio.
 - 2) Covered Towel/Key phone areas are included at each tub area.
- 3) Landscaping will be kept to a minimum. No deciduous trees, some alpine fir and easy maintenance shrubs/grasses. We will stay away from planting that sheds leaves.
- 4) Low level lighting is included for pathways and security and will take into consideration adjacent owners' units.
- 5) Upper Tier Area Eliminated bump out table seating hardscape, removed a portion of hardscape to create a larger buffer between private patio and upper tier. Staircase from upper tier to mid-tier shifts East and is reduced to 6 feet wide. Maintain upper tier area as low as possible to meet ADA access requirements.
- 6) Lower Tier Area Modified locations of tubs and increased size of one tub to 9X12, eliminated walls and surface area is reduced. Eliminated stairs from the Owner's patio to the lower tier.

Cost Estimate Option 1: \$2,553,246.00 Cost Estimate Option 2: \$2,241,400.00 Cost Difference: \$ 311,846.00

Once a selection is made, the Spa Committee and our Construction Team will continue to look for savings as we move forward.

5. PROJECT FUNDING: Option 1: The 3 Tub bid is \$2,553,246.00 and Option 2: came in at \$2,241,400.00

As stated in the most recent Email, both bids have contingency line items from \$138,000 to\$159,000. At these levels, there is upward protection from costs going higher while potential allowing cost savings overall. Additionally, our construction consultants will be continuously monitoring cost savings in all areas that could develop during the construction process. An example would entail a search for lower cost tubs from an overseas manufacturer. Our design build contractor, Lydig Construction, is fully on board with these review efforts and will assist our research.

There are several factors now existing which will allow the Board to offer creative funding alternatives. The Needles owners have already contributed \$260,000.00 which has been placed in reserves specifically for the spa project. The recent savings of over \$200,000.00 in the insurance budget for 2024 further provides flexibility in financial planning. The existing dues structure additionally can be evalrated for uses and needs. As a result, the Board will be looking at two primary choices for project funding as follows:

- 1) Full assessment of either option approved based on unit percentage of ownership prescribed by the CC&Rs. A spreadsheet of assessment per unit allocations will be provided to the members prior to the special meeting.
- 2) This funding option would include loan financing for up to one half of the project cost. The remaining funding will be a reduced assessment. Utilizing some level of dues structure would provide debt servicing of the loan. This would be long term finance amortization

with annual evaluation of any early payoff opportunities. This also allows for Board flexibility with Capex needs unforeseen emergencies and expenses.

SPA COMMITTEE SURVEY REVIEW AND RESULTS

The Spa committee met to review the surveys submitted at the request of the Board. The following are the results of that survey and the Committees recommendation for moving forward.

#1: Don't delay spa project. 70% in favor of moving forward.

#2: Existing capacity is fine for White Pine only. 60% agree. Committee feels that this in not only a capacity issue but a long-term concern for spa and wall failure.

#3 Existing spa are will not meet new capacity with added 5 Needles 75% agree.

#4 Maintance has not been an issue: 50% agree. Spa committee feels this has been an issue and will only continue to get worse.

#5 Are two hot tubs enough? 50% yes 50% no.

#6 Fire pits and two Tubs. Unclear on this line. Other lines clarify.

#7 3 Tubs and no fire pits: 60% in favor.


#8 4 Tubs: 70% no

#9 4 tubs and fire pits. 80% no

#10 Terrace tub levels. 75% yes Design will dictate terracing. Two or Three levels

#11 Additional seating. Inconclusive at this time. It is the committee's recommendation that seating will be added at a later date instead of being built in.

It is the committee's recommendation that we move forward with finalizing the design based on the feed back for the owners with a terraced area with three hot tubs, enlarged seating capacity off of the owner's club and installing a gas line to the owner's club patio for possible future fire pit feature.



WHITE PINES LODGE SPA CONCEPT 10.30.23



WHITE PINES LODGE SPA CONCEPT 3.05.24

NORTH

Bernardo Wills

LYDIG

ARCHITECTURE . INTERIORS . LANDSCAPE ARCHITECT

Spa Condition Commentary

Spa System Operational Concerns

- A. Operations managers and maintenance staff agree that all spas are currently in need of replacement. Daily operations require more sensitive care due to age and condition. The consensus by both present and past Schweitzer Operational Management is that the system is one major repair from being shut down and requiring a major dig or comprehensive CAPEX project. Boiler maintenance costs and labor for maintaining the system has increased year over year and a forecasted MOD is needed.
- B. In 2018 an internal pipe (return feed) failed. Repairs were attempted by DSS construction to reach the failed line. The cost of the initial dig (15 feet) was nearly 15K. DSS stopped midway citing life safety issues. This line was abandoned by Pool World (they utilized jet line) and noted that other lines may be susceptible.
- C. It is suggested to replace the entire system for best operational efficiency. We believe this system to be on fumes for proper and safe operation. Any engineering and replacement proposal (if the wall is not addressed) should include a system (tubs and infrastructure) that has easy access for repairs and future replacement.

Wall Concerns

A. Over the years the top layer of the wall has visibly and notably bowed outward. The evidence is clear, and the AllWest report confirms the need to repair or replace. This condition has led to a shifting of tubs and subsequent cracking of the tubs as well as the concrete around all tub areas. To repair or replace the top 5 layers, the entire spa area would need to be addressed. Current frost /heave issues exist to the point of damage to the slab surface.

Respectfully submitted,

Tom Curtiss, Managing Agent -2004--Present

Shannon May - Schweitzer Maintenance Manager 2007—2023

SPA OPTION 1

| Unit Identification Number | Approximate Square Footage | Undivided Percentage Ownership Interest in Common Area | | | Total Assessment | Needles Adjustment | |
|----------------------------------|----------------------------------|--|----------|----------------------|----------------------------|---------------------------------|----------------------------|
| 107 | 975 | 1.46% | \$ | 3,373.63 | \$40,483.56 | | |
| 108 | 591 | 0.89% | \$ | 2,044.94 | \$24,539.26 | | |
| 109 | 591 | 0.89% | \$ | 2,044.94 | \$24,539.26 \$39,860.73 | | |
| 112 | 960 576 | 1.44% 0.87% | \$ | 3,321.73 1,993.04 | \$23,916.44 | | |
| 201 202 | 556 | 0.84% | s | 1,923.83 | \$23,086.01 | | |
| 203 | 575 | 0.86% | \$ | 1,989.58 | \$23,874.92 | | |
| 204 | 863 | 1.30% | \$ | 2,986.09 | \$35,833.14 \$36,455.96 | | |
| 206 207 | 878 930 | 1.32% 1.40% | \$ | 3,038.00 | \$38,615.08 | | |
| 208 | 842 | 1.26% | \$ | 2,913.43 | \$34,961.18 | | |
| 209 | 568 | 0.85% | \$ | 1,965.36 | \$23,584.27 | | |
| 210 | 867 | 1.30% | \$ \$ | 2,999.94 1,958.44 | \$35,999.22 \$23,501.22 | | |
| 211 212 | 566 866 | 0.85% 1.30% | \$ | 2,996.48 | \$35,957.70 | | |
| 301 | 576 | 0.87% | \$ | 1,993.04 | \$23,916.44 | | |
| 302 | 556 | 0.84% | \$ | 1,923.83 | \$23,086.01 | | |
| 303 | 575 | 0.86% | \$ | 1,989.58 | \$23,874.92 \$23,874.92 | | |
| 304 305 | 575 599 | 0.86% | \$ | 2,072.62 | \$24,871.44 | | |
| 306 | 582 | 0.87% | \$ | 2,013.80 | \$24,165.57 | | |
| 307 | 930 | 1.40% | \$ | 3,217.92 | \$38,615.08 | | |
| 308 | 842 | 1.26% | S | 2,913.43 1,965.36 | \$34,961.18 \$23,584.27 | | |
| 309 | 568 867 | 0.85% 1.30% | s | 2,999.94 | \$35,999.22 | | |
| 310 311 | 566 | 0.85% | \$ | 1,958.44 | \$23,501.22 | | |
| 312 | 866 | 1.30% | \$ | 2,996.48 | \$35,957.70 | | |
| 401 | 576 | 0.87% | \$ | 1,993.04 | \$23,916.44 \$23,086.01 | | |
| 402 403 | 556 575 | 0.84% 0.86% | s | 1,989.58 | \$23,874.92 | | |
| 404 | 575 | 0.86% | \$ | 1,989.58 | \$23,874.92 | 2 | |
| 405 | 599 | 0.90% | \$ | 2,072.62 | \$24,871.44 | | |
| 406 | 582 | 0.87% | \$ | 2,013.80 3,217.92 | \$24,165.57 \$38,615.08 | | |
| 407 408 | 930 842 | 1.40% 1.26% | Š | 2,913.43 | \$34,961.18 | | |
| 409 | 568 | 0.85% | \$ | 1,965.36 | \$23,584.27 | | |
| 410 | 867 | 1.30% | \$ | 2,999.94 | \$35,999.22 | | |
| 411 | 566 | 0.85% 1.30% | \$ | 1,958.44 2,996.48 | \$23,501.22 \$35,957.70 | | |
| 412 501 | 866 976 | 1.47% | \$ | 3,377.09 | \$40,525.08 | | × |
| 502 | 556 | 0.84% | \$ | 1,923.83 | \$23,086.01 | | |
| 503 | 766 | 1.15% | s | 2,650.46 | \$31,805.54 \$43,763.76 | | |
| 504 | 1054 | 1.58% 1.32% | \$ | 3,646.98 | \$36,455.96 | | |
| 506 507 | 878 1207 | 1.81% | \$ | 4,176.38 | \$50,116.5 | | |
| 508 | 609 | 0.91% | \$ | 2,107.22 | \$25,286.65 | | |
| 509 | 568 | 0.85% | \$ | 1,965.36 | \$23,584.2° \$47,002.4 | | |
| 510 | 1132 | 1.70% 0.85% | \$ | 3,916.87 1,958.44 | \$23,501.2 | | |
| 511 512 | 566 592 | 0.89% | s | 2,048.40 | \$24,580.79 | 9 | Total Needles Units |
| 114 | 922 | 1.38% | \$ | 3,190.24 | \$38,282.9 | | \$28,762.66 |
| 115 | 911 | 1.37% | \$ | 3,152.18 | \$37,826.1 | | \$28,419.50 |
| 116 | 899 | 1.35% | \$ | 3,110.66 | \$37,327.9 | Control Control Control Control | \$28,045.15 |
| 117 | 922 | 1.38% | \$ | 3,190.24 | \$38,282.9 | | \$28,762.66 \$10,980.97 |
| 118 | 352 | 0.53% | \$ | 1,217.97 4,231.74 | \$14,615.6 \$50,780.9 | | \$38,152.64 |
| 119 | 1223 | 1.84% | s | 3,190.24 | \$38,282.9 | | \$28,762.66 |
| 214 215 | 922 911 | 1.37% | \$ | 3,152.18 | \$37,826.1 | | \$28,419.50 |
| 216 | 899 | 1.35% | S | 3,110.66 | \$37,327.9 | | \$28,045.15 |
| 217 | 922 | 1.38% | s | 3,190.24 | \$38,282.9 | | \$28,762.66 |
| 218 | 352 | 0.53% | S | 1,217.97 | \$14,615.6 | 0 \$3,634.63 | \$10,980.97 |
| 219 | 1214 | 1.82% | \$ | 4,200.60 | \$50,407.2 | | \$37,871.87 |
| 314 | 922 | 1.38% | \$ | 3,190.24 | \$38,282.9 | | \$28,762.66 |
| 315 | 911 | 1.37% | S | 3,152.18 | \$37,826.1 | | \$28,419.50 |
| 316 | 899 | 1.35% | \$ | 3,110.66 | \$37,327.9 | | \$28,045.15 \$28,762.66 |
| 317 | 922 | 1.38% | \$ | 3,190.24 | \$38,282.9 | | \$10,980.97 |
| 318 | 352 | 0.53% | s | 1,217.97 | \$14,615.6 \$51,030.0 | | \$38,339.81 |
| 319 | 1229 | 1.85% | S | 4,252.50 | | | \$43,206.38 |
| 414 | 1385 | 2.08% | S | 4,643.50 | | | \$41,864.95 |
| 415 416 | 1342 657 | 0.99% | \$ | 2,273.31 | \$27,279.6 | | \$20,495.73 |
| 417 | 660 | 0.99% | \$ | 2,283.69 | | 20 000 100 E-240 DE- | \$20,589.32 \$40,960.27 |
| 418 | 1313 | 1.97% | \$ | 4,543.15 | | | \$43,923.88 |
| 419 | 1408 | 2.11% | \$ \$ | 4,871.87 2,024.18 | | | \$18,249.63 |
| 420 | 585 2146 | 0.88% 3.22% | s | 7,425.45 | | | \$66,946.49 |
| 421 | | 92.36% | \$ | 212,770.50 | | 0 | |
| Residential Sub-Total | 61492 182 | 0.27% | s | - | | 284 | |
| CU2 | 1101 | 1.65% | S | - | | | |
| CU3 | 447 | 0.67% | S | - | | | |
| CU4 | 451 2202 | 0.68% 3.31% | \$ \$ | | | | |
| CU5 CU6 | 703 | 1.06% | s | 900 | | | |
| Commercial Sub-Tota | | 7.64% | \$ | | | | |
| Grand Total | 66578 | 100% | | | | | |
| (of all Units) | | | | | | | |

SPA OPTION 2

White Pine Lodge

| Unit Identification Number | Approximate Square Footage | Undivided Percentage Ownership Interest in Common Area | | Monthly | Total As | sessment | Needles Adjustment | Total |
|----------------------------------|----------------------------------|--|--------|----------------------|----------|----------------------------|--------------------|----------------------------|
| 407 | 075 | 1.46% | \$ | 2,961.58 | | \$35,539.01 | | |
| 107 108 | 975 591 | 0.89% | Š | 1,795.18 | | \$21,542.11 | | |
| 109 | 591 | 0.89% | 5 | 1,795.18 | | \$21,542.11 | | |
| 112 | 960 | 1.44% | \$ | 2,916.02 | | \$34,992.26 | | |
| 201 | 576 | 0.87% | \$ | 1,749.61 | | \$20,995.36 | | |
| 202 | 556 | 0.84% | \$ | 1,688.86 | | \$20,266.35 | | |
| 203 | 575 | 0.86% | \$ | 1,746.58 2,621.38 | | \$20,958.91 \$31,456.58 | | |
| 204 206 | 863 878 | 1.30% 1.32% | \$ | 2,666.94 | | \$32,003.34 | | |
| 207 | 930 | 1.40% | \$ | 2,824.90 | | \$33,898.75 | | |
| 208 | 842 | 1.26% | \$ | 2,557.59 | | \$30,691.13 | | |
| 209 | 568 | 0.85% | \$ | 1,725.31 | | \$20,703.75 | | |
| 210 | 867 | 1.30% | \$ | 2,633.53 1,719.24 | | \$31,602.38 \$20,630.85 | | |
| 211 212 | 566 866 | 0.85% 1.30% | \$ | 2,630.49 | | \$31,565.93 | | |
| 301 | 576 | 0.87% | \$ | 1,749.61 | | \$20,995.36 | | |
| 302 | 556 | 0.84% | \$ | 1,688.86 | | \$20,266.35 | in the second | |
| 303 | 575 | 0.86% | \$ | 1,746.58 | | \$20,958.91 | | |
| 304 | 575 | 0.86% | \$ | 1,746.58 | | \$20,958.91 \$21,833.71 | | |
| 305 | 599 | 0.90% | \$ | 1,819.48 1,767.84 | | \$21,033.71 | | |
| 306 307 | 582 930 | 0.87% 1.40% | \$ | 2,824.90 | | \$33,898.75 | | |
| 308 | 842 | 1.26% | \$ | 2,557.59 | | \$30,691.13 | | |
| 309 | 568 | 0.85% | \$ | 1,725.31 | | \$20,703.75 | | |
| 310 | 867 | 1.30% | \$ | 2,633.53 | | \$31,602.38 | | |
| 311 | 566 | 0.85% | \$ | 1,719.24 2,630.49 | | \$20,630.85 \$31,565.93 | | |
| 312 | 866 | 1.30% 0.87% | \$ | 1,749.61 | | \$20,995.36 | | |
| 401 402 | 576 556 | 0.84% | Š | 1,688.86 | | \$20,266.35 | | |
| 403 | 575 | 0.86% | \$ | 1,746.58 | | \$20,958.91 | | |
| 404 | 575 | 0.86% | \$ | 1,746.58 | | \$20,958.91 | | |
| 405 | 599 | 0.90% | \$ | 1,819.48 | | \$21,833.71 | | |
| 406 | 582 | 0.87% | \$ | 1,767.84 2,824.90 | | \$21,214.06 \$33,898.75 | | |
| 407 | 930 842 | 1.40% 1.26% | \$ | 2,557.59 | | \$30,691.13 | | |
| 408 409 | 568 | 0.85% | \$ | 1,725.31 | | \$20,703.75 | | |
| 410 | 867 | 1.30% | \$ | 2,633.53 | | \$31,602.38 | | |
| 411 | 566 | 0.85% | \$ | 1,719.24 | | \$20,630.85 | | |
| 412 | 866 | 1.30% | S | 2,630.49 | | \$31,565.93 | | x |
| 501 | 976 | 1.47% | \$ | 2,964.62 1,688.86 | | \$35,575.46 \$20,266.35 | | • |
| 502 | 556 766 | 0.8 4 % 1.15% | \$ | 2.326.74 | | \$27,920.91 | | |
| 503 504 | 1054 | 1.58% | \$ | 3,201.55 | | \$38,418.58 | | |
| 506 | 878 | 1.32% | \$ | 2,666.94 | | \$32,003.34 | • | |
| 507 | 1207 | 1.81% | \$ | 3,666.29 | | \$43,995.48 | | |
| 508 | 609 | 0.91% | \$ | 1,849.85 | | \$22,198.21 | | |
| 509 | 568 | 0.85% | \$ | 1,725.31 3,438.48 | | \$20,703.75 \$41,261.7 | | |
| 510 | 1132 566 | 1.70% 0.85% | \$ | 1,719.24 | | \$20,630.85 | | |
| 511 512 | 592 | 0.89% | 5 | 1,798.21 | | \$21,578.56 | | |
| 114 | 922 | 1.38% | \$ | 2,800.60 | U] | \$33,607.15 | | \$24,086.89 |
| 115 | 911 | 1.37% | S | 2,767.18 | ij. | \$33,206.20 | \$9,406.67 | \$23,799.52 |
| 116 | 899 | 1.35% | \$ | 2,730.73 | 8 | \$32,768.79 | \$9,282.76 | \$23,486.03 |
| 117 | 922 | 1.38% | \$ | 2,800.60 | Ď. | \$33,607.15 | | \$24,086.89 |
| 118 | 352 | 0.53% | \$ | 1,069.21 | | \$12,830.5 | | \$9,195.86 |
| 119 | 1223 | 1.84% | \$ | 3,714.89 | | \$44,578.6 | | \$31,950.40 \$24,086.89 |
| 214 | 922 | 1.38% | \$ | 2,800.60 | | \$33,607.1 | | \$23,799.52 |
| 215 | 911 | 1.37% | \$ | 2,767.18 | | \$33,206.2 \$32,768.7 | | \$23,486.03 |
| 216 | 899 | 1.35% | \$ | 2,730.73 | | \$32,766.7 | 점 기가에게 되었으면 | \$24,086.89 |
| 217 | 922 | 1.38% | s s | 2,800.60 1,069.21 | | \$12,830.5 | | \$9,195.86 |
| 218 | 352 | 0.53% | | | | | | \$31,715.28 |
| 219 | 1214 | 1.82% | S | 3,687.55 | | \$44,250.6 | | \$24,086.89 |
| 314 | 922 | 1.38% | \$ | 2,800.60 | | \$33,607.1 | | \$23,799.52 |
| 315 | 911 | 1.37% | \$ | 2,767.18 | | \$33,206.2 | | \$23,486.03 |
| 316 | 899 | 1.35% | \$ | 2,730.73 | | \$32,768.7 \$33,607.1 | | \$24,086.89 |
| 317 | 922 | 1.38% | \$ | 2,800.60 1,069.21 | | \$12,830.5 | | \$9,195,86 |
| 318 | 352 | 0.53% | \$ | | | \$44,797.3 | | \$32,107.15 |
| 319 | 1229 | 1.85% | \$ | 3,733.12 4,206.97 | | \$50,483.6 | | \$36,182.59 |
| 414 | 1385 | 2.08% | \$ | 4,076.36 | | \$48,916.2 | | \$35,059.23 |
| 415 | 1342 657 | 2.02% 0.99% | \$ | 1,995.65 | | \$23,947.8 | 3 \$6,783.96 | \$17,163.87 |
| 416 417 | 660 | 0.99% | \$ | 2,004.76 | | \$24,057.1 | 8 \$6,814.93 | \$17,242.25 |
| 418 | 1313 | 1.97% | \$ | 3,988.27 | 7 | \$47,859.2 | | \$34,301.62 |
| 419 | 1408 | 2.11% | \$ | 4,276.83 | | \$51,321.9 | | \$36,783.46 |
| 420 | 585 | 0.88% | \$ | 1,776.95 | | \$21,323.4 | | \$15,282.90 \$56,063.42 |
| 421 | 2146 | 3.22% | \$ | 6,518.52 | 2 | \$78,222.2 | 8 \$22,158.86 | \$50,005.42 |
| Residential Sub-Total | 61492 | 92.36% | \$ | 186,783.3 | 3 \$ 2 | 2,241,400.00 |) | |
| CU1 | 182 | 0.27% | \$ | * | | | | |
| CU2 | 1101 | 1.65% | \$ | 2 | | | | |
| CU3 | 447 | 0.67% | \$ | 64 | | | | |
| CU4 | 451 | 0.68% 3.31% | \$ | | | | | |
| CU5 CU6 | 2202 703 | 1.06% | \$ | | | | | |
| Commercial Sub-Total | | 7.64% | \$ | | | | | |
| Grand Total (of all Units) | 66578 | 100% | | | | | | |
| | | | | | | | | |